1521-1523 Central Avenue (Commercial Building) Cincinnati Hamilton County Ohio

HABS No. OH-703

0140 0140 01-21NT

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form (0-920 (June 1983)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HARS GHIO 31-CINT

ARCHITECTURAL DATA FORM

STATE	COUNTY		TOWN OR VICINITY	
Ohio ·	Hamilton		Cincinnati	
HISTORIC NAME OF STRUCTURE (INCLUOE SOURCE FOR NAME)				HABS NO.
1521-1523 Central Avenue (Commercial Building)			ОН-703	
SECONDARY OR COMMON NAMES OF S	TRUCTURE	All and a second se		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)				
1521-1523 Central Avenue, Cincinnati, Ohio 45214				
DATE OF CONSTRUCTION (INCLUDE SO	OURCE)	ARCHITECT(S) (INCLU	JDE SOURCE)	
Circa 1890-1895		Unknown		
SIGNIFICANCE (ARCHITECTURAL ANO HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) The four-story commercial/residential structure is located at the corner of Central Avenue and John Street. It is part of a cohesive cluster of other commercial/residential structures which are representative of the Central Avenue streetscape. The area was once a thriving neighborhood business district. STYLE (IF APPROPRIATE) High Victorian Gothic decorative elements				
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) Stone foundation, brick walls of stretcher bond, slate and shingle roof				
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)				
Irregular				
EXTERIOR FEATURES OF NOTE Bracketed cornice with decorative frieze. Stone belt courses delineate each floor. Additional stone banding beneath second, third, and fourth story windows. Three pilasters divide the facade vertically. Decorative window hoods in a six bay (2-1-1-2) configuration on second, third, and fourth floors. Ground floor cast iron				
INTERIOR FEATURES OF NOTE (DESCRI	IBE FLOOR PLANS	CIENOLNKEICHEDL	storefront wi letailing on	th decorative
No interior features of note.			lecalling on	poses.
MAJOR ALTERATIONS AND ADDITIONS	WITH DATES			· · · · · · · · · · · · · · · · · · ·
Storefronts have been altered	1.			
PRESENT CONDITION AND USE				
Good condition; vacant				
OTHER INFORMATION AS APPROPRIAT	E			
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)				
Personal observation Hamilton County Courthouse				
COMPILER, AFFILIATION			DA	i
Lauren Blank, Historic Conser	vation Office	, City Planning Co	mmission M	March 18, 1982